



Picture 1 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Concrete barnyard outside the main barn.



Picture 2 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Drain hole in the concrete curb at the southern end of the barnyard.





Picture 3 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Barnyard runoff flows downhill into a small drainage ditch.



Picture 4 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Small drainage ditch that receives runoff from the concrete barnyard.





Picture 5 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Vegetated swale that receives runoff from the small ditch described in pictures #3-4.



Picture 6 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Broken concrete, leaks from the large silage bunker.





Picture 7– Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Broken concrete, leaks from the large silage bunker.



Picture 8 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Roadside drainage ditch #2 on the west side of the dirt road, which receives silage runoff.





Picture 9 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Runoff/leachate from the small silage pile across from the main barn.



Picture 10 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Runoff/leachate from small silage pile across from the main barn.





Picture 11 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Runoff direction from the small silage pile in pictures # 9-10, (looking east).



Picture 12 – Allendale Farm, 2357 Jersey Street, Pantton, VT – 09/19/13  
Mortality compost pile, located on the east side of the dirt road at the edge of the field.